

DRY STORAGE PROCEDURES

Before Arrival at the Marina	<ul style="list-style-type: none"> Use the GCCM (Marine Master) App or call Marina on 07 5502 5888 at least one hour before your arrival. Office hours are 8am – 5pm, 7 days. Closed Good Friday & Christmas Day Quote your full name and rack number to the customer service team Specify if the boat is to be “Launched” or if the boat is to go to a “Wash Cradle” Ensure your account is up to date (Vessels with accounts or agreements in arrears will not be lifted) Ensure insurance policy is up-to-date and GCCM has a copy (Vessels without COC on profile will not be lifted)
Upon Arrival at Marina	<ul style="list-style-type: none"> Unload your gear at the unloading carpark directly in front of customer lounge No vehicles to be driven in front of the dry storage building Park your car in the long-term car park NO SMOKING within 50 metres of Dry Storage building or berths No admittance to the Dry Storage building under any circumstance All children are to be accompanied by an adult at all times Display caution whilst around machinery operating area
Returning to Marina	<ul style="list-style-type: none"> Use the GCCM (Marine Master) App or phone office on 07 5502 5888 at least one hour before your arrival (if arriving after hours, Security will answer 07 5508 5888) Inform DS Crew if the boat is to be “Return to Rack” or if the boat is to go to a “Wash Cradle” Trim outboard or stern drive leg up, ensure trim tabs are up Speedos and Transducers must be pulled up All aerials, biminis and wakeboard towers are to be lowered Any lights on top of vessel to be lowered Ensure all battery switches are in “OFF” or “ISOLATED” position Use GCCM app, or call Reception or put a ‘return to rack’ or ‘return to wash cradle’ sign on the boat. Vessels must move from the courtesy dock with to be left on the courtesy dock for extended period
While on a Wash Down Cradle 1 DAY LIMIT	<ul style="list-style-type: none"> Wash cradles are to be used for general upkeep or hose down only – 1 day All maintenance and repairs are to be done to EPA (Environmental Protection Authority) guidelines on the shipyard (Charges apply) Place all rubbish in the appropriate bins provided Notify DS Crew or Reception if your boat needs to be on wash cradle for any more than one hour (Max 1 hour on weekend & Public Holidays) No toxic degreasers or detergents to be used in this area Please use your own engine muffs & hose fittings Ensure bungs are left in at all times NO SMOKING within 50 metres of Dry Storage Building or Berths Use the GCCM (Marine Master) App, call Reception or put a ‘return to rack’ sign on the boat when the boat is ready to go back to rack GCCM accepts no liability for any damage or theft to/ from your vessel whilst out of Dry Store on wash cradle or hardstand due to contractors or third parties All aerials, biminis and wakeboard towers are to be lowered Any lights on top of vessel to be lowered
General Information	<ul style="list-style-type: none"> All vessels must have a “Battery Isolation Switch” and be turned off in the Dry Store If using lithium batteries GCCM only accepts lithium iron phosphate batteries in Dry Storage No gas cylinders permitted on any vessel Ensure bungs are left in at all times Amenities including laundry, drinks and snacks located at the customer lounge If your vessel is in the water, make sure your auto bilge pump switch is on Children (12 and under) and pets are to remain in the vessel or customer lounge when a vessel is on the wash cradle.
Test & Tag	<ul style="list-style-type: none"> All electrical equipment (i.e. tools, electrical cords etc.) must have a current test and tag as required by law under <i>AS/NZS 3760 In-service safety inspection and testing of electrical equipment, and the Queensland Electrical Safety regulation 2013</i>. In a marine environment, electrical equipment and cords should be tested every 6 months.

I as the owner of the vessel known as

Boat name: / Rego

I have read the above points & understand them clearly and I have received a copy of these procedures.

SIGNED DATE